A	rea/Activity Assessed	Outbuildings – Nursery Annex			Date	Completed	23.01.24		
А	ssessment Completed					w Date on(s) Consulted	23.01.25 Rob Beard (Site Manager – Jayne Ecclestone (Finance Manager)		
F	ersons Exposed requency of Exposure uration of Exposure	EmployeesContractorsYoung PersonContinuallyHourlyDailyLess than 1hr1-2 hrs3-4 hrs			Mo We	ther an	Visitors d/or PublicTrespassersMonthlyYearly7-8 hrsMore than 8 hrs		
	Probability 5= Very Likely, 4= Likely, 3= Quite Possible, 2= Possible, 1= Unlikely L Severity 5= Catastrophic, 4= Major, 3= Moderate, 2= Minor, 1= Insignificant H					0-8 Low risk no action required 9-15 Medium risk ensure adequate controls are in use 16-25 High risk stop operation and implement adequate control measures			
No	Hazard	Re Existing Control Measures			l Risk Risk		Additional Control Measures		
1.	Slips, trips and falls	 All employees are aware of the need for good housekeeping throughout the premises. All access routes, walkways and general floor areas are suitably illuminated using an appropriate level of lighting. Appointed cleaning maintains the office and welfare areas on a daily basis including the cleaning of floor surfaces. Floor surfaces of the premises areas are subject to on-going visual inspections by all employees throughout the working day. Designated walkways have been established where appropriate and all employees are aware that they must remain free from obstruction. 			9		access to the kitchenette has a trip hazard as the eeling upward. Advise a larger floor plate is used to he hazard.		



	Hazard	Existing Control Measures		sidua	Risk	
No				Probability	Risk	Additional Control Measures
		 On-going supervision completed by nominated personnel who ensure employees are adhering to safe working practices. 				
2.	Electrocution	 Fixed electrical installation inspected. Equipment in excellent condition. Shutters are maintained by an external contractor annually. PAT testing completed annually. 	5	1	5	
3.	Fire	 Fire Risk Assessment completed in accordance with the Regulatory Reform (Fire Safety) Order 2005. The assessment considers the provision of preventative measures, means of raising the alarm, staff training and provision of firefighting equipment. All alarm and emergency lighting systems are maintained by appointed competent contractor. Smoking prohibited in the building in line with current legislation. Fire extinguishers present. All escape routes are unobstructed. Sources of ignition and combustible items kept apart. 	5	2	10	 Fire stop required around the flexible extractor pipe leading into the ceiling void. Advise this is filled with flame retardant expanding foam or cut to size fireboard.
4.	Cuts, bumps and bruises	 Equipment in good condition. Low level storage. First Aid available on site and fully stocked. 	3	3	9	 Disabled toilet is used for the storage of materials. Toilets should not be used for storage to ensure items cannot fall and cause an injury. Radiator cover is not secured to the wall. Advise strong fixing are pit into place to stop the radiator cover falling forward and causing an injury.



			Residual Risk			
No	Hazard	Existing Control Measures		Probability	Risk	Additional Control Measures
5.	Housekeeping	Regular cleaning procedure in place.Rubbish is removed by appointed cleaning.Rubbish bins are emptied daily.	3	1	3	
6.	Contamination caused by poor hygiene (toilets, welfare areas) Staff may suffer from ill health issues due to contamination of welfare areas e.g. sickness, exposure to legionella or similar virus	 The areas are subject to cleaning regime. Stored water systems are subject to an on- going monitoring regime to ensure that they remain free from Legionella bacteria. Bi-Annual risk assessment completed. A/C units are serviced on an annual basis. 	3	3	9	 Disabled toilet is used for the storage of materials. Toilets should not be used for storage to ensure good hygiene practices.
7.	Un-authorised Access	 Visitors are required to report to reception and sign into a register. All visitors are accompanied throughout the building at all times unless a valid DBS has been presented. Access is restricted to authorised site staff. 	3	3	9	 Storeroom is currently used for hazardous COSHH materials which is unsecure. Advise access is restricted by either locking or placing a lock on the door.
8.	Exposure to Asbestos Containing Materials (ACM's) Exposure to inhalable or ingestible ACM fibres could lead to Asbestos related disease for those affected	 Location of ACM's was established by previous survey. ACM's are subject to on-going monitoring by the school management team following the guidance provided by the survey. ACM register information is given to all outside contractor personnel who may be required to work in the location where ACM's are present. 	5	1	5	
9.	СОЅҤН	 Substances controlled by competent personnel. Staff are trained in the safe use of COSHH. COSHH assessments completed. SDS and COSHH file available on site. 	3	2	6	

Compliance Education

ACTIONS ARISING FROM THE RISK ASSESSMENT									
Hazard number	control measures?		When will the actions be complete?	Date complete and any comments or note					
1.1	Med Site Team 1 M		1 Month						
3.1	Med	Site Team	1 Month						
4.1&6.1	Med	Site Team	1 Month						
4.2	Med	Site Team	1 Month						
7.1	Med	Site Team	1 Month						



Acknowledgement The following members of staff have read this risk assessment. Their signatures are confirmation that they have read and understood all which is within its contents.

Name	Signature	Date	Name	Signature	Date

